



**Anderson-Cottonwood Irrigation District
Operations Report
August 8 –September 12**

Remove Tree from Olney Creek





Clean bank in area



Missouri Tree









Re-install fence



Livestock Damage Repair



Repair
complete



Lateral 27 – Hopson Rd.



CCB – Hefflin Ditch 2000ft





Main Canal Breach







Washout







River Flows

8728 CFS

Canal Flows

235 CFS

Churn Creek

Bottom

55 CFS

The river is ramping down.

Season is coming to a close.

Looking forward to a productive off season

Thank you!!!